

Tech Tool

Tech ToolLinksHelp

PAPPU KUMAR


ProductProduct HistoryDiagnoseTestCalibrateProgram

1. Leak test

Leak test



Clutch information



☒ Clutch Cylinder Position [mm]

☒ Clutch Actuator Fast Disengage...

☒ Clutch Actuator Fast Engage[%]

☒ Clutch Actuator Slow Disengage...

☒ Clutch Actuator Slow Engage[%]

40083-3 PWM valves clutch

Information >> Conditions >> Execution

599 rpmEngine speed

842 kPaAir pressure

Action

1. Leak test

Start the test

Check that the value is within limits and the status light turns green

Note! This action takes about 45 seconds to perform

0 mmValue before test

0 mmValue after test

Continue >

Chassis ID: 8 991632 VIN: YV2XBZ0G5R8991632 Work Order: V-68

Product Online



ENG IN

12:48 PM 8/5/2025

Tech Tool

Tech ToolLinksHelp

PAPPU KUMAR


ProductProduct HistoryDiagnoseTestCalibrateProgram

1. Leak test

Leak test



Clutch information



☒ Clutch Cylinder Position [mm]

☒ Clutch Actuator Fast Disengage...

☒ Clutch Actuator Fast Engage[%]

☒ Clutch Actuator Slow Disengage...

☒ Clutch Actuator Slow Engage[%]

40083-3 PWM valves clutch

Information >> Conditions >> Execution

606 rpmEngine speed

842 kPaAir pressure

Action

1. Leak test

Start the test

Check that the value is within limits and the status light turns green

Note! This action takes about 45 seconds to perform

22.8 mmValue before test

22.7 mmValue after test

Continue >

 CHURCH CYMRU CYMDEITHAS FYDD


■ **Church Accused of Not Disengaging...**

Clutch Actuator Fast Engage[%]

Clutch Actuator Slow Disengage...

Clutch Actuator Slow Engage[%]

2. Clutch performance test



40083-3 PWM valves clutch

Information >> Conditions >> **Execution**

595 rpm

Engine speed

838 kPa

Air pressure

Action

1. Leak test

- Start the test
- Check that the value is within limits and the status light turns green

 **Note!** This action takes about 45 seconds to perform

22.8 mm

Value before test

22.7 mm

Value after test

Continue >