

VIN: YV2XBZ0G7R8991390 Mileage: 69100.8 km
Chassis ID: 8 991390 Printed: 14/10/2025 11:44
Model: FM (4)
Reg. Number:



Fault Tracing : ECM - P1021 - 13, Volvo Compression Brake (VCB) Control Circuit - Circuit Open

Start Time: 14/10/2025 16:13:32	End Time: 14/10/2025 17:07:27	Status: No fault found Session ID: 8991390141039465	Work Order: 1543	User ID: M793749	Partner ID: IN069123
---	---	--	----------------------------	----------------------------	--------------------------------

DTC Readout :

Start Time: 14/10/2025 11:16:19	Session ID: 8991390141039465	Work Order: 1543	User ID: M793749	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

DTC Readout :

Start Time: 14/10/2025 11:16:09	Session ID: 8991390141039465	Work Order: 1543	User ID: M793749	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

DTC Readout :

Start Time: 14/10/2025 11:16:04	Session ID: 8991390141039465	Work Order: 1543	User ID: M793749	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

DTC Readout :

Start Time: 14/10/2025 11:15:58	Session ID: 8991390141039465	Work Order: 1543	User ID: M793749	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

DTC Readout :

Start Time: 14/10/2025 11:15:50	Session ID: 8991390141039465	Work Order: 1543	User ID: M793749	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

DTC Readout :

Start Time: 14/10/2025 10:39:46	Session ID: 8991390141039465	Work Order: 1543	User ID: M793749	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

Control Unit Information :

Start Time: 14/10/2025 10:39:46	Session ID: 8991390141039465	Work Order: 1543	User ID: M793749	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

DTC Readout :

Start Time: 13/10/2025 16:20:18	Session ID: 8991390131616530	Work Order: 1543	User ID: M793749	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

DTC Clear :

Start Time: 13/10/2025 16:20:10	Session ID: 8991390131616530	Work Order: 1543	User ID: M793749	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

Control Unit Information :

Start Time: 13/10/2025 16:16:53	Session ID: 8991390131616530	Work Order: 1543	User ID: M793749	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

DTC Readout :

User ID: M793749

Partner ID: IN069123

Page 1 of 3

User name: Saroj Kumar Sahu

Partner name: Volvo Service & Parts Centre, Korba

VIN: YV2XBZ0G7R8991390 Mileage: 69100.8 km
Chassis ID: 8 991390 Printed: 14/10/2025 11:44
Model: FM (4)
Reg. Number:



Start Time: 13/10/2025 16:16:38	Session ID: 8991390131616530	Work Order: 1543	User ID: M793749	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

DTC Readout :

Start Time: 22/03/2025 16:57:31	Session ID: 8991390221653227	Work Order: 1543	User ID: MB08813	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

DTC Clear :

Start Time: 22/03/2025 16:57:27	Session ID: 8991390221653227	Work Order: 1543	User ID: MB08813	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

DTC Clear :

Start Time: 22/03/2025 16:56:36	Session ID: 8991390221653227	Work Order: 1543	User ID: MB08813	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

DTC Readout :

Start Time: 22/03/2025 16:56:01	Session ID: 8991390221653227	Work Order: 1543	User ID: MB08813	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

Calibration : 40070-3 - Gearbox, clutch, engagement point

Start Time: 22/03/2025 16:54:32	End Time: 22/03/2025 16:55:55	Status: Passed Session ID: 8991390221653227	Work Order: 1543	User ID: MB08813	Partner ID: IN069123
---	---	--	----------------------------	----------------------------	--------------------------------

DTC Readout :

Start Time: 22/03/2025 16:53:29	Session ID: 8991390221653227	Work Order: 1543	User ID: MB08813	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

Control Unit Information :

Start Time: 22/03/2025 16:53:22	Session ID: 8991390221653227	Work Order: 1543	User ID: MB08813	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

Fault Tracing : TECU - P1075 - 38, Clutch System - Signal Frequency Incorrect

Start Time: 22/03/2025 15:45:33	End Time: 22/03/2025 15:53:40	Status: No fault found Session ID: 8991390221011493	Work Order: 1543	User ID: MB08813	Partner ID: IN069123
---	---	--	----------------------------	----------------------------	--------------------------------

DTC Readout :

Start Time: 22/03/2025 10:26:01	Session ID: 8991390221011493	Work Order: 1543	User ID: MB08813	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

DTC Clear :

Start Time: 22/03/2025 10:25:57	Session ID: 8991390221011493	Work Order: 1543	User ID: MB08813	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

Test : 40083-3 - PWM valves clutch

User ID: M793749

Partner ID: IN069123

Page 2 of 3

User name: Saroj Kumar Sahu

Partner name: Volvo Service & Parts Centre, Korba

VIN: YV2XBZ0G7R8991390 Mileage: 69100.8 km
Chassis ID: 8 991390 Printed: 14/10/2025 11:44
Model: FM (4)
Reg. Number:



Start Time: 22/03/2025 10:19:26	End Time: 22/03/2025 10:22:53	Status: Not Passed Session ID: 8991390221011493	Work Order: 1543	User ID: MB08813	Partner ID: IN069123
---	---	--	----------------------------	----------------------------	--------------------------------

Control Unit Information :

Start Time: 22/03/2025 10:11:49	Session ID: 8991390221011493	Work Order: 1543	User ID: MB08813	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------

DTC Readout :

Start Time: 22/03/2025 10:11:34	Session ID: 8991390221011493	Work Order: 1543	User ID: MB08813	Partner ID: IN069123
---	--	----------------------------	----------------------------	--------------------------------